



September 26, 2001

## **TECHNICAL SERVICE BULLETIN # CM0002**

**Attention:**           **Service Managers**

**Subject:**           **Important Information**  
**Final Coat Corrosion Control**  
**Module #CM-2000**

It is important to make sure that all CM-2000 Rust Control Modules have an **in-line fuse installed**, as this will protect the unit from damage from any voltage surges.

In-line fuses were standard on all units shipped after August 20, 2000. However, we have found that dealers have not rotated inventory or have removed the fuse from the modules, therefore please check on inspection.

When inspecting a previously installed CM-2000 Final Coat Rust Control Module, **please insure that there is an in-line fuse connected to the Rust Module.**

Five (5) quick connect in-line fuse plugs are enclosed.

Please call, if you have any questions or require additional in-line fuse plugs.

(800) 387-3760  
(905) 660-9615